CORRES. CONTROL				
OUTGOING LTR. NO.				
DOE ORDER # 4700.1				
05-RF-002	70			
DIST.	LTR			
DIETER, T.J.	Ŀ			
ERRERA, D.W.	Х			
JNDSAY, D.C.				
.ONG, J.				
YLE, J.L.				
MARTINEZ, L. A.				
AZZUTO, V.M.				
SHELTON, D.C.				
SPEARS, M.S.		i		
UOR, N. R.				
		L		
	Ш	Ĺ		
• '.	Ш			
BEAN, C.	Ш			
DECK, C.		Ļ		
OSS, D.				
RANCIS, M.				
REIBOTH, C.	X			
BEIS, A.				
3IBBS, F.	X			
IUMISTON, T.				
(NAPP, S.				
AVORATO, K.				
INSINBIGLER, H.				
NYERS, K.				
JESTA, S.	X	X		
ORTH, K.		_		
MAN, K.				
LAPPERT, R.				

'RIMROSE, A. RICHARDELLA, R.

NYDER, D.P. WARTZ, J.M.

VARD, D.A. VIEMELT, K. ILLS, S. HULER, K.

ORRES.CONTROL DMIN RECRD/T130G

RAFFIC

ATS/130

CNI **NCLASSIFIED** ONFIDENTIAL

ECRET



March 14, 2005

05-RF-00270

Gary Morgan, Functional Lead Cadre Project Management Division DOE, RFPO

TRANSMITTAL OF CLOSE OUT REPORT FOR BUILDING - T130G - FEG-006-05

Attached is the Closeout Report for the Type 1 facility Building T130G - Office Trailer. Please note that a copy of the report has been submitted to the CERCLA AR by the Kaiser-Hill RISS project.

Please contact Steve Nesta x6386 with questions or concerns.

Tuler Till

Frank E. Gibbs

Deputy Project Manager

Remediation, Industrial D&D, and Site Services

Attachment:

As Stated

SMN:pvt

Orig. and 1 cc - Gary Morgan

UTHORIZED CLASSIFIER


SIGNATURE: 4/10 FRETBURG

ACTION ITEM STATUS: PARTIAL/OPEN

CLOSED

ORIG. & TYPIST INITIALS: SMN:pvt

Joseph Legare Deanna McCranie



F-46469(Rev.9/94)

admin record

Type 1 Facility Closeout Report

Section A. Facility Data				
Facility No.	T130G	•		
Facility Descriptor:		quare feet		
Project:	Office Trailer, 15,400 square feet RISS – Area 5 D&D			
Date of Demolition:	February 24, 2005			
		etal office trailer demolished and disposed of as sanitary waste.		
Additional Information:				
(Must include information on e	environmeniai reieases ana	conditions of site at turnover to Environmental Restoration)		
Section B. Final Charac	terization Data			
Reconnaissance Level Cha		Reconnaissance Level Characterization Report -		
(concurrence received)		Concurrence, Steven H. Gunderson to Joseph A. Legare,		
(00,10111111111111111111111111111111111		dated April 22, 2003.		
In-process Characterization	n.	N/A		
Pre-Demolition Survey Re		N/A		
Post-Demolition Survey Re		N/A		
Post-Demontion Survey Re	eport (as necessary)	1VA		
Section C. Waste Data (complete categories as	appropriate)		
Sanitary Disposal				
Disposal Site:	BFI Foot	hills Landfill, Golden, Colorado		
Waste Volume (m ³):				
Waste Weight (tons):	2660 Cubic yards 602.94 tons			
Additional Information:		Above grade building debris		
Additional information.	· Above gi	ade building debits		
Hazardous Disposal				
Disposal Site:	Kettlema	n Hills Facility, Kettleman City, CA or Bethlehem Apparatus		
_	Co, Helle	ertown, PA		
Waste Volume (m ³):	Minor an	nounts		
Additional Information:	Electroni	c circuit boards, thermostats, exit signs, batteries, fluorescent		
		os and any other RCRA hazardous components were removed		
		to the RFCA temporary unit for combination with like waste		
		or disposal.		
				
TSCA Waste Disposal	-			
Disposal Site:	27/4			
Waste Volume (m ³):	N/A			
Additional Information:				
Asbestos Waste Disposal				
Disposal Site:				
Waste Volume (m ³):	N/A	· · · · · · · · · · · · · · · · · · ·		
Additional Information:				
Additional Information.	-			
Low-Level Waste Disposal				
Disposal Site:				
Waste Volume (m ³):	_N/A			
Additional Information:	; ·			
Law Lavel Mixed Weste D	ionocol			
Low-Level Mixed Waste D	isposai			
Disposal Site:	N/A			
Waste Volume (m³):	III IN/A			
Additional Information:	ـــــــــــــــــــــــــــــــــــــ	<u> </u>		
Recycled Material				
Recycle Facility:	100			
Waste Volume (m³):				
Additional Information:				

Type 1 Facility Closeout Report

Property Disposition Receiver Locations (major items only):	N/A	
Volume (m³): Weight (tons): Additional Information:		
Section D. Approvals	FREIMM Juna	65/10/05 Date

Additional Facility Information

Building T130G was an approximately 15,400 square foot modular trailer acquired in 1991. The structure was corrugated metal siding with corrugated metal skirting. The entrances had wooden stairs leading to a wooden enclosure.

Building T130G had the following utilities: electrical, plant water, plant sanitary and fire protection provided by an overhead sprinkler system and wall mounted fire extinguishers.

The entire T130G structure was removed during D&D activities, and sent offsite for disposal. The utilities were disconnected and removed to at least three feet below final grade as indicated on the attached map. There are no remaining structural components, utility lines, or parts of the foundation. The buildings are not in an IHSS or PAC therefore no soil sampling is required.

